

**ILSSI
Green Belt
Practice
Exam
Questions**

Q1: What method is used to increase confidence level in the results of a DOE ?

- A Sequencing
- B Replication
- C Blocking
- D Regression

Q2: If the correlation coefficient is between 0.5 to 1, it means there is a

- A Negative correlation
- B No correlation
- C Positive correlation
- D A&B

Q3: What is the best description of a hypothesis test?

- A A tool for deciding if Statistical Significance exists between data samples
- B A tool for dissecting the data
- C A tool for brainstorming problems
- D A tool for breaking up the problem in smaller parts

Q4: Which hypothesis test is similar to the 1 sample t-test but is used when the data set is non-normal?

- A 1- sample sign
- B Kruskal-Wallis
- C Friedman
- D Mann-Whitney

Q5: Who is often called the 'Father of quality control'?

- A W. Edwards Deming
- B F. Deming Edwards
- C Dennis Edwards
- D W. Frederick Deming

Q6: A typical linear regression equation would look like

- A Yield = 100%
- B $Y = a + bx$
- C $3.4 = \text{DPMO}$
- D all of the above

Q7: Which one of the following would NOT be considered a COMMON CAUSE VARIATION in a process? (choose the best answer)

- A Serious workplace accidents that cause a shutdown for more than 2 hours
- B Changes in the moods of customers every day that effect ticket sales
- C Regular daily changes in average outside temperature that effect ice-cream sales
- D The number of cars that pass a drive-through fast-food restaurant per hour during the hours 12pm – 1pm each day

Q8: Which of the following activities is an example of non-value-added?

- A Rework
- B Inspection
- C Packing
- D Setup

Q9: What is the Japanese word for waste?

- A Mode
- B Muri
- C Muda
- D Mura

Q10: Which of these is NOT a Measure of Central Tendency or Position of a process?

- A Inter Quartile Range
- B Mean
- C Mode
- D Median

Q11: What is the middle value in a data set when arranged in numerical order?

- A Variance
- B Median
- C Mean
- D Mode

Q12: A Lean Six Sigma Green Belt practitioner constructs a control chart to display a process mean and its outer limits. In such a chart, what does UCL stand for?

- A Upper Control Length
- B Upper Control Limit
- C Upper Cycle Limit
- D Upper Cycle Length

Q13: Which of the following is true about Control Limits and Specification Limits?

- A Control limits are set by the customer
- B Specification limits are set by the process owner
- C It is best practice to set Control Limits narrower than Specification limits
- D A suitable control chart and the right control limits will help to differential special cause variation from common cause variation.

Q14: Which one of the following statements most accurately describes the following string of numbers?

1.2, 1.4, 1.4, 1.8

- A The mean is 1.45 and the SD approximately 0.22
- B The mean is 1.44 and the SD is 0.685
- C The mean is 1.1 and the SD is about 0.4
- D The mean is 1.45 and the SD is 0.827

Q15: The p-value for a Moods Median test is 0.02 and the level of significance is set at 0.05, what decision is made?

- A Use a different test
- B Fail to reject null hypothesis
- C Cannot determine
- D Reject null hypothesis

Q16: What does SPC stand for?

- A Standard Process Charting
- B Statistical Process Control
- C Standard Planning for Control
- D System Performance Charting

Q17: A process with a process Sigma level of 6 over the long term would be expected to produce which of the following?

- A Approximately 3.4 defects per 1 Million Products
- B Approximately 3.4 defects per 1 Million Defect Opportunities
- C Approximately 3.4 defects per 1 Million Success Opportunities
- D Approximately 3.4 defects per 1 Million Process Opportunities

Q18: In Lean Six Sigma, we generally consider 2 categories of variation in processes. Which of the following are the correct 2 categories?

- A Significant Variation and Practical variation
- B Special Cause Variation and Common Cause variation
- C Critical Cause Variation and Random Variation
- D Significant Cause Variation and Low Variation

Q19: What is the minimum level of training that the member of a Lean Six Sigma process improvement team requires ?

- A Black Belt
- B Master Black Belt
- C Yellow Belt
- D Green Belt

Q20: Value Stream Mapping is a technique that is considered to be part of the tool-kit from which methodology?

- A Kaizen
- B Lean
- C BPR
- D Six Sigma

Q21: Understanding “the voice of the customer” is a technique used to provide customers with _____:

- A Cheaper products and services
- B Buy one get one free offers
- C Best in class quality
- D Services and products that meet the customer expectations and needs

Q22: A product or service that does not meet the expectations of the customer is called a _____

- A Defective product or service
- B Defect
- C Problem
- D Reject

Q23: It is always important to understand who is the customer of a process. Which of the following is the best definition of 'The Customer'?

- A Anyone who supplies products or services to the process
- B Stakeholders of the process
- C Anyone who receives a product or service, or could receive a product of service from the process
- D People or groups who are responsible for the output of the process.

Q24: What Lean Six Sigma tool is used to organise and create order in the layout of the tools and equipment in the workplace?

- A SMED
- B 5S
- C Kanban
- D Muda

Q25: The Lean Six Sigma concept called 'Critical to Quality' (CTQ) always focuses on what?

- A Reducing product variation
- B reducing in-process inventories and minimizing product touch times
- C Meeting the specific requirements of the customer
- D Minimizing shipping damage

Q26: The name of an approved written plan of the expected benefits to the business and the expected savings achieved from running a Lean Six Sigma project is called a _____

- A Project business case
- B Project charter
- C Savings document
- D Project budget

Q27: What is the name of the technique used where a company measures its performance against that of best-in-class companies?

- A Run Chart
- B Six Sigma
- C Control Chart
- D Benchmarking

Q28: What basic quality tools would be most applicable for a work team to use when there is a need to follow procedures and work instructions more closely?

- A Fishbone Diagrams and control charts
- B Data sheets and histograms
- C Pareto Charts and affinity diagrams
- D Standard operating instructions and visual management

Q29: One of the purposes of using a fishbone diagram is to

- A Define the problem in sequential order
- B Show the relationship between parameters
- C Identify the root causes of a problem
- D Separate a problem into smaller components

Q30: Which of the following control charts would be best to use for a process in which measurement data on a product is easily and inexpensively obtained?

- A p-charts
- B X-bar charts
- C Median charts
- D I-charts

Q31: Full Factorial and Fractional Factorial are both _____

- A DOE designs
- B OFAT designs
- C Sigma designs
- D Print designs

Q32: Which of the following is the best mathematical representation for a 2-level full factorial designed experiment containing 4 factors?

- A 2×4
- B K^2
- C 3^k
- D 2^4

Q33: What is an experimental factor?

- A A dependent variable
- B An input variable for a designed experiment
- C A metric of a process
- D A standard deviation

Q34: A _____ equation describes the relationship between a Response Variable (Y) and a Predictor Variable (X)?

- A Linear
- B Correlation
- C Regression
- D Non-Linear

Q35: Which of the following statements is most true about Long Term process variation compared to short term variation ?

- A Long term variation contains all forms of variation in the process
- B They are both the same
- C Short term variation contains all forms of variation in the process
- D Long term variation is always double (2 times) that of short term variation

Q36: Which of the following errors in a Hypothesis test is typically associated with a "False Positive"?

- A Depends on the experiments
- B Type I error
- C Type II error
- D Type III error

Q37: Which item should not be identified in the Define Phase?

- A Stakeholders
- B Root causes
- C The key problem area
- D Business Case

Q38: Which of the following distributions is characterized by the Empirical Rule (68 / 95 / 99.7 rule)?

- A Chi-square
- B Normal
- C Student's test
- D F statistic

Q39: In a brainstorming session, an effective facilitator should never:

- A Encourage the participation of all members
- B Dismiss ideas in the early stages
- C Dismiss discouraging remarks
- D Encourage adherence to a structure

Q40: How is takt time calculated?

- A Available time divided by demand
- B Demand divided by the amount of time available
- C Time required for a task divided by demand
- D Overall process time minus time required for a particular task

Q41: How many experimental runs would be required in a full factorial design if there are two (2) levels and six (6) factors?

- A 32
- B 12
- C 64
- D 6

Q42: Which measure of a statistical distribution relates to how much it is equally balanced on each side of the mode?

- A Skewness
- B Standard deviation
- C Kurtosis
- D Central tendency


Q43: All of the following are components of a multiple regression model EXCEPT:

- A Blocks
- B Correlation coefficients
- C Residuals
- D Intercept

Q44: Which statement is correct about the Capability Analysis shown in Figure 1 (below)?

- A There were 100 parts used in this capability study
- B The Standard Deviation for part diameter is 0.00100746
- C This distribution is Skewed.
- D The upper specification limit is 5.05 mm

Figure 1:



Q45: Which statement is correct about the Capability Analysis shown in Figure 1 (above)?

- A From this study we can predict that this process will produce less than 100 parts per million that are outside of the specification limits
- B The process has a problem with centering.
- C The parts have a mean average diameter between 4 mm and 4.9 mm
- D The process needs significant improvements to be in control

Q46: Finish this sentence:

As part of Lean Six Sigma improvement in processes we aim to reduce the “Batch and Queue” method of production and move towards a _____ method of production

- A Single Team Flow
- B Single Piece Flow
- C Fluid Flow
- D SPC

Q47: Which element of waste best describes the unnecessary movement of materials and / or finished goods?

- A Motion
- B Inventory
- C Transport / Conveyance
- D Over processing

Q48: A technique used to dramatically reduce the time to change one tool set-up to another is called _____

- A Perfection
- B SMED
- C Overproduction
- D Defect

Q49: Which of the 7 wastes identified by Taiichi Ohno describes the waste of a downstream worker who cannot continue the next step of a process until a large batch has finished processing in the upstream operation

- A Over production
- B Over processing
- C Waiting
- D Motion

Q50: Which of the following are considered to be the pioneers and “fathers” of Quality Improvement and Statistical Process Control methods?

- A Steve Jobs, Bill Gates
- B Richard Branson, Alan Sugar
- C Joseph Juran, W. Edwards Deming, Walter Shewart
- D Jack Welch, Sam Walton

**Green Belt
Practice
Exam
Questions
with
Answers
(In Green)**

Q1: What method is used to increase confidence level in the results of a DOE ?

- A Sequencing
- B Replication
- C Blocking
- D Regression

Q2: If the correlation coefficient is between 0.5 to 1, it means there is a

- A Negative correlation
- B No correlation
- C Positive correlation
- D A&B

Q3: What is the best description of a hypothesis test?

- A A tool for deciding if Statistical Significance exists between data samples
- B A tool for dissecting the data
- C A tool for brainstorming problems
- D A tool for breaking up the problem in smaller parts

Q4: Which hypothesis test is similar to the 1 sample t-test but is used when the data set is non-normal?

- A 1- sample sign
- B Kruskal-Wallis
- C Friedman
- D Mann-Whitney

Q5: Who is often called the 'Father of quality control'?

- A W. Edwards Deming
- B F. Deming Edwards
- C Dennis Edwards
- D W. Frederick Deming

Q6: A typical linear regression equation would look like

- A Yield = 100%
- B $Y = a + bx$
- C 3.4 = DPMO
- D all of the above

Q7: Which one of the following would NOT be considered a COMMON CAUSE VARIATION in a process? (choose the best answer)

- A Serious workplace accidents that cause a shutdown for more than 2 hours
- B Changes in the moods of customers every day that effect ticket sales
- C Regular daily changes in average outside temperature that effect ice-cream sales
- D The number of cars that pass a drive-through fast-food restaurant per hour during the hours 12pm – 1pm each day

Q8: Which of the following activities is an example of non-value-added?

- A Rework
- B Inspection
- C Packing
- D Setup

Q9: What is the Japanese word for waste?

- A Mode
- B Muri
- C Muda
- D Mura

Q10: Which of these is NOT a Measure of Central Tendency or Position of a process?

- A Inter Quartile Range
- B Mean
- C Mode
- D Median

Q11: What is the middle value in a data set when arranged in numerical order?

- A Variance
- B Median
- C Mean
- D Mode

Q12: A Lean Six Sigma Green Belt practitioner constructs a control chart to display a process mean and its outer limits. In such a chart, what does UCL stand for?

- A Upper Control Length
- B Upper Control Limit
- C Upper Cycle Limit
- D Upper Cycle Length

Q13: Which of the following is true about Control Limits and Specification Limits?

- A Control limits are set by the customer
- B Specification limits are set by the process owner
- C It is best practice to set Control Limits narrower than Specification limits
- D A suitable control chart and the right control limits will help to differential special cause variation from common cause variation.**

Q14: Which one of the following statements most accurately describes the following string of numbers?

1.2, 1.4, 1.4, 1.8

- A The mean is 1.45 and the SD approximately 0.22**
- B The mean is 1.44 and the SD is 0.685
- C The mean is 1.1 and the SD is about 0.4
- D The mean is 1.45 and the SD is 0.827

Q15: The p-value for a Moods Median test is 0.02 and the level of significance is set at 0.05, what decision is made?

- A Use a different test
- B Fail to reject null hypothesis
- C Cannot determine
- D Reject null hypothesis**

Q16: What does SPC stand for?

- A Standard Process Charting
- B Statistical Process Control**
- C Standard Planning for Control
- D System Performance Charting

Q17: A process with a process Sigma level of 6 over the long term would be expected to produce which of the following?

- A Approximately 3.4 defects per 1 Million Products
- B Approximately 3.4 defects per 1 Million Defect Opportunities**
- C Approximately 3.4 defects per 1 Million Success Opportunities
- D Approximately 3.4 defects per 1 Million Process Opportunities

Q18: In Lean Six Sigma, we generally consider 2 categories of variation in processes. Which of the following are the correct 2 categories?

- A Significant Variation and Practical variation
- B Special Cause Variation and Common Cause variation**
- C Critical Cause Variation and Random Variation
- D Significant Cause Variation and Low Variation

Q19: What is the minimum level of training that the member of a Lean Six Sigma process improvement team requires ?

- A Black Belt
- B Master Black Belt
- C Yellow Belt
- D Green Belt

Q20: Value Stream Mapping is a technique that is considered to be part of the tool-kit from which methodology?

- A Kaizen
- B Lean
- C BPR
- D Six Sigma

Q21: Understanding “the voice of the customer” is a technique used to provide customers with _____:

- A Cheaper products and services
- B Buy one get one free offers
- C Best in class quality
- D Services and products that meet the customer expectations and needs

Q22: A product or service that does not meet the expectations of the customer is called a _____

- A Defective product or service
- B Defect
- C Problem
- D Reject

Q23: It is always important to understand who is the customer of a process. Which of the following is the best definition of 'The Customer'?

- A Anyone who supplies products or services to the process
- B Stakeholders of the process
- C Anyone who receives a product or service, or could receive a product of service from the process
- D People or groups who are responsible for the output of the process.

Q24: What Lean Six Sigma tool is used to organise and create order in the layout of the tools and equipment in the workplace?

- A SMED
- B 5S
- C Kanban
- D Muda

Q25: The Lean Six Sigma concept called 'Critical to Quality' (CTQ) always focuses on what?

- A Reducing product variation
- B reducing in-process inventories and minimizing product touch times
- C Meeting the specific requirements of the customer
- D Minimizing shipping damage

Q26: The name of an approved written plan of the expected benefits to the business and the expected savings achieved from running a Lean Six Sigma project is called a _____

- A Project business case
- B Project charter
- C Savings document
- D Project budget

Q27: What is the name of the technique used where a company measures its performance against that of best-in-class companies?

- A Run Chart
- B Six Sigma
- C Control Chart
- D Benchmarking

Q28: What basic quality tools would be most applicable for a work team to use when there is a need to follow procedures and work instructions more closely?

- A Fishbone Diagrams and control charts
- B Data sheets and histograms
- C Pareto Charts and affinity diagrams
- D Standard operating instructions and visual management

Q29: One of the purposes of using a fishbone diagram is to

- A Define the problem in sequential order
- B Show the relationship between parameters
- C Identify the root causes of a problem
- D Separate a problem into smaller components

Q30: Which of the following control charts would be best to use for a process in which measurement data on a product is easily and inexpensively obtained?

- A p-charts
- B X-bar charts
- C Median charts
- D I-charts

Q31: Full Factorial and Fractional Factorial are both _____

- A DOE designs
- B OFAT designs
- C Sigma designs
- D Print designs

Q32: Which of the following is the best mathematical representation for a 2-level full factorial designed experiment containing 4 factors?

- A 2×4
- B K^2
- C 3^k
- D 2^4

Q33: What is an experimental factor?

- A A dependent variable
- B An input variable for a designed experiment
- C A metric of a process
- D A standard deviation

Q34: A _____ equation describes the relationship between a Response Variable (Y) and a Predictor Variable (X)?

- A Linear
- B Correlation
- C Regression
- D Non-Linear

Q35: Which of the following statements is most true about Long Term process variation compared to short term variation ?

- A Long term variation contains all forms of variation in the process
- B They are both the same
- C Short term variation contains all forms of variation in the process
- D Long term variation is always double (2 times) that of short term variation

Q36: Which of the following errors in a Hypothesis test is typically associated with a "False Positive"?

- A Depends on the experiments
- B Type I error
- C Type II error
- D Type III error

Q37: Which item should not be identified in the Define Phase?

- A Stakeholders
- B Root causes
- C The key problem area
- D Business Case

Q38: Which of the following distributions is characterized by the Empirical Rule (68 / 95 / 99.7 rule)?

- A Chi-square
- B Normal
- C Student's test
- D F statistic

Q39: In a brainstorming session, an effective facilitator should never:

- A Encourage the participation of all members
- B Dismiss ideas in the early stages
- C Dismiss discouraging remarks
- D Encourage adherence to a structure

Q40: How is takt time calculated?

- A Available time divided by demand
- B Demand divided by the amount of time available
- C Time required for a task divided by demand
- D Overall process time minus time required for a particular task

Q41: How many experimental runs would be required in a full factorial design if there are two (2) levels and six (6) factors?

- A 32
- B 12
- C 64
- D 6

Q42: Which measure of a statistical distribution relates to how much it is equally balanced on each side of the mode?

- A Skewness
- B Standard deviation
- C Kurtosis
- D Central tendency


Q43: All of the following are components of a multiple regression model EXCEPT:

- A Blocks
- B Correlation coefficients
- C Residuals
- D Intercept

Q44: Which statement is correct about the Capability Analysis shown in Figure 1 (below)?

- A There were 100 parts used in this capability study
- B The Standard Deviation for part diameter is 0.00100746
- C This distribution is Skewed.
- D The upper specification limit is 5.05 mm**

Figure 1:



Q45: Which statement is correct about the Capability Analysis shown in Figure 1 (above)?

- A From this study we can predict that this process will produce less than 1 part per million that are outside of the specification limits**
- B The process has a problem with centering.
- C The parts have a mean average diameter between 4 mm and 4.9 mm
- D The process needs significant improvements to be in control

Q46: Finish this sentence:

As part of Lean Six Sigma improvement in processes we aim to reduce the “Batch and Queue” method of production and move towards a _____ method of production

- A Single Team Flow
- B Single Piece Flow**
- C Fluid Flow
- D SPC

Q47: Which element of waste best describes the unnecessary movement of materials and / or finished goods?

- A Motion
- B Inventory
- C Transport / Conveyance
- D Over processing

Q48: A technique used to dramatically reduce the time to change one tool set-up to another is called _____

- A Perfection
- B SMED
- C Overproduction
- D Defect

Q49: Which of the 7 wastes identified by Taiichi Ohno describes the waste of a downstream worker who cannot continue the next step of a process until a large batch has finished processing in the upstream operation

- A Over production
- B Over processing
- C Waiting
- D Motion

Q50: Which of the following are considered to be the pioneers and “fathers” of Quality Improvement and Statistical Process Control methods?

- A Steve Jobs, Bill Gates
- B Richard Branson, Alan Sugar
- C Joseph Juran, W. Edwards Deming, Walter Shewhart
- D Jack Welch, Sam Walton

